

**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021

Project: Maple Elementary / Middle School **NPDES NO:** MAR1002G4 **DEP NO:** 151-0305

To: City of Easthampton Conservation Commission - Attn: Cassie Tragert

50 Payson Avenue, Easthampton, MA 01027

Construction Representative : David Boucher

Project Phone: (Cell) 413-237-6577

Email Address: david.boucher@colliers.com

Project Address: 200 Park Street

Easthampton, MA 01027

=====
Date of Inspection: 06/25/21 **Inspection Start Time:** 7:30AM **Inspection End Time:** 8:10AM

Weather Conditions: 61 DF L.Showers **Construction Phase:** Building Construction

- **Was inspection triggered by a 0.25" storm event?** No
 - **Was a stormwater discharge occurring from any part of site during inspection?** No
- =====


Project Activity Summary:

- Roofing
- Exterior sheathing
- Interior framing
- MEP
- Brick veneer
- Storefront/Windows
- Interior Finishes

Erosion Control Statements

- 1) The integrity of the erosion controls remains intact on the site.

Attachments: 7-Pictures




**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021



To the left of entrance.




**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021



Right side to entrance of site.




**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021



Right side before entering the site.




**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021



The stream. (It's clear)




**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021



Looking up entrance drive. (Grass planted).




**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021



Bio-retention at rear.



**WEEKLY CONSERVATION COMMISSION
EROSION CONTROL REPORT**

Week of: June 25, 2021



Looking North at Bio-Retention.